


## TECH TIPS



***THE 3 FOCUS POINTS RELATIVE TO SUCCESSFUL PAINT PERFORMANCE!***

### **“THE 15 DEGREE RULE”**

ESTABLISHES 70 DEGREES AND 50% RELATIVE HUMIDITY AS THE STANDARD TEMPERATURE FOR PAINT DRYING TIMES AS PER LABEL INSTRUCTIONS.

FOR EVERY 15 DEGREES **ABOVE** 70 DEGREES, DRY TIME & POT LIFE IS CUT IN HALF!

FOR EVERY 15 DEGREES **BELOW** 70 DEGREES DRY TIME & POT LIFE IS DOUBLE!

NOTES TO REMEMBER: **THIN** PAINT DRIES FASTER THAN **THICK** PAINT!

TWO COMPONENT CROSS LINKING STOPS  
**BELOW** 60 DEGREES!